ROAD SAFETY AUDIT

Warren Avenue at Market Street

Brockton, Massachusetts

May 6, 2022

Prepared through Old Colony MPO FFY 2022 Unified Planning Work Program – Road Safety Audits at Multiple Locations: Under Contract with MassDOT



Prepared By: Old Colony Planning Council 70 School Street, Brockton, MA. 02301



Table of Contents

Contents

Background	1
Project Data	1
Project Location and Description	2
Audit Observations and Potential Safety Enhancements	4
Summary of Road Safety Audit	6

List of Appendices

Appendix A.	RSA Meeting Agenda
Appendix B.	RSA Audit Team Contact List
Appendix C.	Detailed Crash Data

Appendix D. Additional Information

List of Tables

Table 1: Participating Audit Team Members	2
Table 2: Estimated Time Frame and Costs Breakdown	
Table 3: Potential Safety Enhancement Summary	7

Background

This Road Safety Audit for Warren Avenue at Market Street was prepared as part of the Old Colony Metropolitan Planning Organization's (MPO) Road Safety Audits at Multiple Locations project in the MPO's FFY 2022 Unified Planning Work Program. The objective of the Road Safety Audits at Multiple Locations project is to identify known issues and potential improvements that can be implemented at high crash locations in a continuing effort to achieve safety performance targets for reducing serious injuries and fatalities on the regional highway network. Locations were selected through a data driven process as part of the MPO's Safety Management System and consultation with the communities of the Old Colony MPO.

Project Data

This Road Safety Audit was held on May 6, 2022. Out of an abundance of caution and respect to the health and safety of Audit participants, this Road Safety Audit was conducted virtually through a webinar format. Participants were provided crash data and associated analysis (crash characteristics charts, collision diagrams) prior to the Audit for review, and background traffic data (traffic volumes and travel speeds) along with surrounding land use were discussed during the Audit.

During the audit, crash analysis, land use, and traffic data were discussed. Aerial photographs of the intersection along with ground level photographs were provided.

A five-year crash history from January 1, 2017 through December 31, 2021 was analyzed and provided to audit participants. Based on MassDOT and Brockton Police Department data and reports, there were 80 crashes in this five-year period. Sixty-seven (84%) of those crashes were angled collisions, while 57 (71%) involved vehicles traveling in the northbound direction on Warren Avenue. Twenty-five (31%) of crashes occurred outside of daylight hours. Over half of the crashes resulted in injury.

The RSA participants formed a multidisciplinary team representing many fields, including planning and engineering. A list of RSA attendees is shown in Table 1.

Audit Team Member	Agency/Affiliation
Brady Winsten	City of Brockton – Policy and Intergovernmental Affairs
Jay DeGrace	City of Brockton – Constituent Services Liasson
John Fay	City of Brockton – Planning
Chief Brian Nardelli	Brockton Fire Department
Michael Damon	Brockton Area Transit (BAT)
Kelly Forrester	Brockton Area Transit (BAT)
Al DiGirolamo	Office of State Senator Michael Brady
Dakota DelSignore	MassDOT Traffic and Safety Engineering Section
Kevin Fitzgerald	MassDOT Traffic and Safety Engineering Section
Raissah Kouame	MassDOT Office of Transportation Planning
Bianca Marshall	MassDOT District Five Traffic
Jason Walters	MassDOT District Five Projects
Michael Medeiros	MassDOT District Five Traffic
Ray Guarino	Old Colony Planning Council
Guoqiang Li	Old Colony Planning Council
Shawn Bailey	Old Colony Planning Council
Kyle Mowatt	Old Colony Planning Council
Bill McNulty	Old Colony Planning Council

 Table 1: Participating Audit Team Members

Project Location and Description

The intersection of Warren Avenue at Market Street is a four-legged unsignalized intersection, with STOP control present on the eastbound approach of Market Street (Market Street is one-way eastbound).

Development around the intersection is high density urban residential. The Warren Avenue Baptist Church is located on the southwest corner, while the Huntington Day School is located on the northwest corner. South Middle School is located one block southwest of the intersection. A playground is also located on the northwest corner of the intersection.

Figure 1 provides an aerial photo of the intersection.

• Warren Avenue: Warren Avenue is a significant north-south connection in the City of Brockton, connecting Downtown Brockton to densely developed residential areas south of Downtown. It is under the jurisdiction of the City of Brockton. It is a two-lane undivided roadway, functionally classified as an Urban Minor Arterial. There are sidewalks on both sides of the roadway. Parking is allowed on Warren Avenue except for the area immediately adjacent to the intersection. There are no special speed regulations for Warren Avenue, however Brockton has a fundamental prima facie speed limit of 30 MPH throughout the City. There is also a 20 MPH School Zone Speed Limit on Warren Avenue through the intersection during school arrival and dismissal times.

• Market Street: Market Street is a one-way (eastbound) local road under jurisdiction of the City of Brockton, it serves as an 0.75-mile-long east-west connection from West Chestnut Street to Montello Street (Route 28). The approach forms two lanes at the intersection: a left turn lane, and a shared right turn and through movement lane. There are sidewalks on both sides of the roadway. There are no special speed regulations for Market Street, however Brockton has a fundamental prima facie speed limit of 30 MPH throughout the City.



Figure 1: Locus Map

Audit Observations and Potential Safety Enhancements

The following safety issues along with potential safety enhancements were identified for the intersection of Warren Avenue at Market Street.

Speed: Of the 80 crashes at this intersection that were analyzed in this Audit, over half of them resulted in injury. Speed of traffic on Warren Avenue could be a significant factor in the severity of crashes occurring at this location. High speeds make it difficult for drivers entering from Market Street to find adequate gaps to enter Warren Avenue, and audit participants noted motorists often accelerate through the intersection due to speed on Warren Avenue. Speed may also be a factor in the high volume of angled collisions, with drivers not having adequate stopping sight distance at prevailing travel speed.

Potential Safety Enhancements:

- 1. *Short Term / Low Cost*: Increased, strict enforcement of existing prima facia speed limit of 30 MPH.
- 2. *Short-Term / Low-Cost*: Establish Safety Zone with 20 MPH Speed Limit on Warren Avenue and Market Street on approaches to intersection. Existing land use featuring a concentration of churches, schools, and a playground in this area supports enactment of a Safety Zone.
- 3. *Mid Term / Medium Cost*: Convert Warren Avenue to a Complete Street design with narrower travel lanes, bike lanes, and bus stops to calm speed and make roadway safer for all users.

Limited or Obstructed Sight Distance: Several features are present at this location that are limiting sight distance towards and from the intersection with Market Street. While parking is prohibited on the immediate corners of the intersection, existing street parking on Warren Avenue is close enough to still obstruct views of approaching traffic on Warren Avenue. The size and location of the sign in front of the Warren Avenue Baptist Church is obstructing the view of northbound traffic. Despite being well set back from the roadway, the sprawling foliage on the northwest corner obstructs sight lines. With the two-lane exit design of Market Street, drivers in the left lane cannot see traffic approaching from Warren Avenue when a vehicle is present next to them in the right lane. Similarly, drivers on the northbound approach of Warren Avenue have difficulty seeing a vehicle in the left lane on Market Street when it is being obscured by a vehicle in the right lane.

Potential Safety Enhancements:

1. *Short-Term / Low-Cost*: Expand and enforce no parking zones around intersection.

- 2. *Short-Term / Low-Cost*: Work with church to either reduce size of sign or relocate sign.
- 3. Short-Term / Low-Cost: Keep tree canopy on northwest corner trimmed back.
- 4. *Mid-Term / Low Cost:* Evaluate converting intersection to all=way stop controlled (STOP signs on Warren Avenue)/
- 5. *Mid-Term / Medium Cost:* Narrow Market Street approach to only one lane. Consider adding parking lane to Market Street for area schools, church, and playground, or physically narrow Market Street with curb and sidewalk extensions at intersection.
- 6. *Long-Term / High Cost:* Consider installation of traffic signals at the intersection, if warranted.

Failure to Stop or Yield Right of Way: Analysis of crash data indicated that either failure to stop at the stop sign on Market Street or failure to yield right of way was a substantial factor in crashes occurring at this location. This was further confirmed by observation during sight visits and audit participants.

It was noted during field observation and conformed by Audit participants that drivers are often confused at the intersection and are under the assumption that all approaches are under STOP control. A motorist on Warren Avenue was observed stopping at the intersection, despite no cross-street traffic on Market Street being present.

Potential Safety Enhancements:

- 1. *Short-Term / Low-Cost*: Install "Cross Traffic Does Not Stop" supplemental placards (MUTCD W4-4P) underneath Market Street STOP signs.
- 2. *Short-Term / Low-Cost*: Increase enforcement on Market Street for compliance with stop condition.
- 3. *Short-Term / Low-Cost*: Enhance the STOP signs on Market Street with higher profile signs, and advance warning signs on both sides of Market Street approaching the intersection. Consider using brighter, high intensity LED bulbs in overhead flashing beacon.
- 4. *Short-Term / Low-Cost*: Install advance warning signage of Warren Avenue to increase driver awareness of intersection ahead.

Lighting: 25 of 80 crashes occurred outside of daylight hours, indicating lighting may be an issue at this location.

Potential Safety Enhancements:

1. *Short-Term, Low-Cost*: Increase nighttime visibility of intersection with retroreflective striping on crosswalks and stop bar.

2. Mid Term / Medium Cost: Improve area lighting.

Pedestrian accommodations: Curb ramps at the intersection are non-ADA compliant, and there is low visibility of the existing standards crosswalk markings. Schools and playgrounds in the area along with dense residential land use and transit stops along Warren Avenue generate a high volume of pedestrians at this intersection. There was one pedestrian-involved crash during the analysis period that resulted in a non-datal injury.

Potential Safety Enhancements:

- 1. *Short-Term / Low-Cost:* Upgrade crosswalks with higher visibility design and striping.
- 2. *Mid-term / Medium Cost*: Consider upgrading curbing and ramps at crosswalks to comply with ADA requirements.

No bicycle accommodations: The roadways do not include any existing bicycle accommodations.

Potential Safety Enhancements:

3. Long term / High Cost: Consider adding bicycle lanes with any planned improvements.

Summary of Road Safety Audit

Based on the review of data, observations of the intersection made in the field, and group discussion, the RSA team identified possible enhancements that could improve safety at the intersection. Further study and design work will need to be conducted to determine the feasibility of improvements. Table 2 summarizes the estimated time frame and costs, and Table 3 summarizes the safety issues, possible enhancements, estimated safety payoff, time frame, cost, and jurisdiction responsibility. Safety payoff estimates are based on engineering judgment and are categorized as low, medium, and high. The time frame is categorized as short-term (<1 year), midterm (1 to 3 years), or long-term (typically >3 years). Long-term improvements are typically considered to be substantial improvements with an expected time frame for implementation greater than 3 years. The costs are categorized as low (<\$10,000), medium (\$10,001 to \$50,000), or high (>\$50,000)."

 Table 2: Estimated Time Frame and Costs Breakdown

Time	Frame		Costs
Short-Term	<1 Year	Low	<\$10,000
Mid-Term	1-3 Years	Medium	\$10,001-\$50,000
Long-Term	>3 Years	High	>\$50,000

Safety Issue	Potential Safety Enhancement	Safety Payoff	Time Frame	Cost	Jurisdiction
Speed	Enforce existing prima facia speed limits	High	Short-Term	Low	City of Brockton
Speed	Establish Safety Zones with 20 MPH Speed Limit	High	Short-Term	Low	City of Brockton
Speed	Implement Complete Streets design on Warren Avenue	High	Mid-Term	Medium	City of Brockton
Sight Distance	Expand non parking zones around intersection	Medium	Short-Term	Low	City of Brockton
Sight Distance	Work with church to relocate or resize sign	Medium	Short-Term	Low	City of Brockton
Sight Distance	Keep tree canopy on northwest corer trimmed back to maximize sight distance	Medium	Short-Term	Low	City of Brockton
Sight Distance	Evaluate feasibility of All-Way Stop Control	High	Mid-Term	Low	City of Brockton
Sight Distance	Narrow Market Street approach to only allow one lane	High	Mid-Term	Medium	City of Brockton
Sight Distance	Reconstruct intersection with traffic signals	High	Long-Term	High	City of Brockton
Failure to Stop or Yield Right of Way	Install "Cross Traffic Does Not Stop" supplemental placards (MUTCD W4-4P) underneath Market Street STOP signs	Medium	Short-Term	Low	City o Brockton
Failure to Stop or Yield Right of Way	Increase enforcement on Market Street for compliance with stop	High	Short-Term	Low	City of Brockton
Failure to Stop or Yield Right of Way	Enhance stop with advance warning signs and oversized stop signs on both sides of roadway	High	Short-Term	Low	City of Brockton

Table 3: Potential Safety Enhancement Summary

Safety Issue	Potential Safety Enhancement	Safety Payoff	Time Frame	Cost	Jurisdiction
Failure to Stop or Yield Right of Way	Install advance warning signage on Warren Avenue	High	Short-Term	Low	City of Brockton
Lighting	Use high visibility retroreflective striping on crosswalks and stop bar to enhance nighttime visibility of intersection		Short-Term	Low	City of Brockton
Lighting	Improve area lighting	Medium	Mid-Term	Medium	City of Brockton
Pedestrian accommodations	Restripe crosswalks with high visibility design	High	Short-Term	Low	City of Brockton
Pedestrian accommodations	Upgrade curbing and ramps at crosswalks to make ADA compliant	Medium	Mid-Term	Medium	City of Brockton
Lack of bicycle accommodations	Consider adding bicycle lanes to Warren Avenue and Market Street	Medium	Mid-Term	Medium	City of Brockton

Appendix A. RSA Meeting Agenda

Participating Audit Team Members

Date: May 6 2022 Lo	ocation: Warren Avenue at Market Street, Brockton					
Audit Team Members	Agency/Affiliation					
Brady Winsten	City of Brockton – Policy and Intergovernmental Affairs					
Jay DeGrace	City of Brockton – Constituent Services Liasson					
John Fay	City of Brockton – Planning					
Chief Brian Nardelli	Brockton Fire Department					
Michael Damon	Brockton Area Transit (BAT)					
Kelly Forrester	Brockton Area Transit (BAT)					
Al DiGirolamo	Office of State Senator Michael Brady					
Dakota DelSignore	MassDOT Traffic and Safety Engineering Section					
Kevin Fitzgerald	MassDOT Traffic and Safety Engineering Section					
Raissah Kouame	MassDOT Office of Transportation Planning					
Bianca Marshall	MassDOT District Five Traffic					
Jason Walters	MassDOT District Five Projects					
Michael Medeiros	MassDOT District Five Traffic					
Ray Guarino	Old Colony Planning Council					
Guoqiang Li	Old Colony Planning Council					
Shawn Bailey	Old Colony Planning Council					
Kyle Mowatt	Old Colony Planning Council					
Bill McNulty	Old Colony Planning Council					

Appendix C. Detailed Crash Data

Crash Data Summary Table Warren Avenue at Market Street, Brockton, MA

2017-2021

Orresh	Creeh	1			2017-2	Weather						
Crash	Crash Date	Crash Day	Time of Day	Manner of Collision	Light Condition	Condition	Road Surface	Driver Contributing Code		Agos		Comments
Diagram Ref #	m/d/y	Crash Day	Time of Day	Type	Type	Туре	Type	Type	D1	Ages D2	D3	comments
1	1/14/17	Saturday	10:05 AM	Angle	Daylight	Clear	Dry	Failed to yield right of way	80	54		17-87-AC
1	1/14/17	Saturday	10.05 AM	Angle	Daylight	Cieai	ыу	Tailed to yield right of way	00	54		17-07-AC
2	3/1/17	Wednesday	5:28 PM	Angle	Dark - lighted roadway	Clear	Dry	Failed to yield right of way	52	53		17-377-AC
3	6/12/17	Monday	4:07 PM	Angle	Daylight	Clear	Dry	Unknown	32	49		17-1087-AC
4		Sunday	6:11 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	22	29		17-1200-AC
5	7/16/17	Sunday	6:12 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	27	43		17-1301-AC
5	1/10/11	Cunady	0.1211	, tigic	Dayiigin	Oleal	Diy	Tailed to yield light of way	21		40	17-1001-40
6	8/5/17	Saturday	10:51 PM	Angle	Dark - lighted roadway	Clear	Dry	Failed to yield right of way	63	25		17-1418-AC
		,			, ,		,	, , , , , , , , , , , , , , , , , , , ,				
7	9/7/17	Thursday	9:25 PM	Angle	Dark - lighted roadway	Clear	Dry	Inattention	18	19		17-1609-AC
8	10/10/17	Tuesday	2:15 AM	Rear-end	Dark - lighted roadway	Clear	Wet	Fatigued/asleep	53			17-1822-AC
9	12/5/17	Tuesday	4:43 PM	Angle	Dark - lighted roadway	Rain	Wet	Failed to yield right of way	24	32		17-2253-AC
10	1/10/18	Wednesday	4:41 PM	Angle	Dusk	Clear	Dry	Unknown	64	39		18-100-AC
11	1/27/18	Saturday	12:45 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	63	22		18-221-AC
12	3/1/18	Thursday	9:56 AM	Angle	Daylight	Clear	Dry	Failed to yield right of way	25	75		18-434-AC
13	3/2/18	Friday	3:22 PM	Angle	Daylight	Rain	Wet	Unknown	19	37		18-441-AC
14	3/15/18	Thursday	9:02 AM	Angle	Daylight	Clear	Dry	No Improper Driving	19	23		18-533-AC
15	4/1/18	Sunday	1:15 PM	Single Vehicle Crash	Daylight	Clear	Dry	No Improper Driving	17	39		18-644-AC
16	5/5/18	Saturday	11:21 PM	Angle	Dark - lighted roadway		Dry	Failed to yield right of way	32	34		18-866-AC
17	5/12/18	Saturday	12:11 PM	Angle	Daylight	Rain	Wet	Failed to yield right of way	44	48		18-913-AC
18	7/14/18	Saturday	6:18 PM	Single Vehicle Crash	Daylight	Clear	Dry	Failed to yield right of way	32	26		18-1331-AC
19	7/20/18	Friday	5:28 PM	Angle	Daylight	Clear	Dry	Inattention	18	60		18-1361-AC
20	8/7/18	Tuesday	2:59 PM	Angle	Daylight	Clear	Dry	Unknown	22	50		18-1480-AC
21	8/23/18	Thursday	7:14 PM	Angle	Dusk	Clear	Dry	Failed to yield right of way	36	34		18-1575-AC
22	9/4/18	Tuesday	8:05 PM	Angle	Dark - lighted roadway	Clear	Dry	Unknown	54	74		18-1657-AC
							_	Disregarded traffic signs, signals, road				
23	9/30/18	Sunday	12:33 PM	Angle	Daylight	Clear	Dry	markings	35	32		18-1818-AC
24	10/19/18		12:42 PM	Angle	Daylight	Clear	Dry	Unknown	31	40		18-1932-AC
25	10/25/18		1:14 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	26	30		18-1966-AC
26	11/5/18	Monday	11:01 AM	Sideswipe, same direction	Daylight	Clear	Dry	Failed to yield right of way	70	60		18-2043-AC
27		Monday	3:08 PM	Sideswipe, same direction	Daylight	Clear	Dry	No Improper Driving	20	39		18-2162-AC
28	12/2/18	Sunday	3:30 PM	Angle	Daylight	Cloudy	Wet	Failed to yield right of way	48	29		18-2241-AC
29	12/10/18	Monday	3:43 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	72	53	•	18-2308-AC
							_					
30	12/22/18	Saturday	10:39 PM	Angle	Dark - lighted roadway	Clear	Dry	Failed to yield right of way	30	49		18-2397-AC
a :	10/01/15		0.00.00									
31	12/24/18	Monday	6:20 PM	Angle	Dark - lighted roadway	Clear	Wet	Failed to yield right of way	63	59		18-2421-AC
20	2/0/40	Caturday	C-27 DM	Angle	Deule lighted as stores	Clear	D	Follog to viold right of way	50	22		10.054.40
32	2/9/19	Saturday	6:37 PM	Angle	Dark - lighted roadway	Clear	Dry	Failed to yield right of way	56	33		19-254-AC

Crash Data Summary Table Warren Avenue at Market Street, Brockton, MA

2017-2021

Crash	Crash				2017-	Weather						
Diagram	Date	Crash Day	Time of Day	Manner of Collision	Light Condition	Condition	Road Surface	Driver Contributing Code		Ages		Comments
Ref #	m/d/y	,		Туре	Туре	Туре	Туре	Туре	D1	D2	D3	
33	2/17/19	Sunday	1:53 PM	Angle	Daylight	Clear	Dry	Unknown	51	22	43	19-291-AC
					, ,			Disregarded traffic signs, signals, road				
34	3/18/19	Monday	12:40 PM	Angle	Daylight	Clear	Dry	markings	26			19-481-AC
35	4/27/19	Saturday	2:03 PM	Angle	Daylight	Cloudy	Dry	Failed to yield right of way	36			19-742-AC
36	6/28/19	Friday	1:35 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	17	65		19-1148-AC
37	7/1/19	Monday	3:50 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	50			19-1173-AC
38		Monday	6:18 AM	Angle	Daylight	Clear	Dry	Failed to yield right of way	71	23		19-1305-AC
39	7/31/19	Wednesday	5:53 PM	Angle	Daylight	Cloudy	Dry	Failed to yield right of way	36			19-1366-AC
40	9/9/19	Monday	6:58 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	49	53		19-1641-AC
41	9/16/19	Monday	8:07 AM	Angle	Daylight	Clear	Dry	Inattention	27	27		19-1683-AC
42	10/6/19	Sunday	10:08 AM	Angle	Daylight	Clear	Dry	No Improper Driving	28	62		19-1815-AC
								Disregarded traffic signs, signals, road				
43		Wednesday	9:29 PM	Angle	Dark - lighted roadway		Wet	markings	28			19-1891-AC
44	11/17/19	Sunday	1:19 PM	Angle	Daylight	Cloudy	Dry	Failed to yield right of way	47	23		19-2133-AC
	40/4/40											10 0074 00
45	12/4/19	Wednesday	5:40 PM	Angle	Dark - lighted roadway		lce	Visibility Obstructed	29	31		19-2274-AC
46		Wednesday	12:13 PM	Angle	Daylight	Clear	Wet	Failed to yield right of way	41	63		19-2330-AC
47	1/14/20	Tuesday	3:53 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	16			20-77-AC
48	1/15/20	Wednesday	9:00 AM	Angle	Daylight	Clear	Dry	Failed to yield right of way	52			20-80-AC
49	1/20/20	Monday	4:21 PM	Angle	Dawn	Clear	Dry	Failed to yield right of way	34	19		20-134-AC
50	2/11/20	Tuesday	5:20 PM	Single Vehicle Crash	Dark - lighted roadway	Clear	Wet	Unknown	49	41		20-260-AC
51	7/2/20	Thursday	10:15 PM	Angle	Dark - lighted roadway	Clear	Dry	Failed to yield right of way	43			20-891-AC
52	8/7/20	Friday	4:24 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	43	32		20-1080-AC
53	8/13/20	Thursday	5:16 PM	Sideswipe, opposite direction	Daylight	Clear	Dry	Failed to yield right of way	23			20-1132-AC
54	9/5/20	Saturday	12:25 PM	Angle	Daylight	Clear	Dry	No Improper Driving	51	44		20-1260-AC
55	9/7/20	Monday	8:18 PM	Angle	Dusk	Clear	Dry	Unknown	20	26		20-1281-AC
56	10/17/20	Saturday	3:24 AM	Single Vehicle Crash	Dark - lighted roadway	Rain	Wet	Unknown	35	19		20-1514-AC
57	11/5/20	Thursday	5:16 PM	Angle	Dark - lighted roadway	Clear	Dry	Failed to yield right of way	24	69		20-1654-AC
58	11/18/20	Wednesday	6:45 PM	Angle	Dark - lighted roadway	Clear	Dry	Failed to yield right of way	21	44		20-1719-AC
59	12/2/20	Wednesday	1:15 PM	Angle	Daylight	Clear	Dry	Unknown	44	65		20-1811-AC
60	12/2/20	Wednesday	5:29 PM	Single Vehicle Crash	Dark - lighted roadway	Clear	Dry	Unknown	36			20-1813-AC
61	12/5/20	Saturday	5:47 AM	Sideswipe, same direction	Dark - lighted roadway	Rain	Wet	Failed to yield right of way	31	37		20-1833-AC
						L .	l	Disregarded traffic signs, signals, road	-			
62	12/5/20	Saturday	10:39 AM	Angle	Daylight	Rain	Wet	markings	29			20-1835-AC
63	12/11/20	Friday	6:22 AM	Angle	Daylight	Clear	Dry	Failed to yield right of way	28			20-1868-AC
64	12/22/20	Tuesday	10:44 AM	Angle	Daylight	Clear	Dry	Failed to yield right of way	23	22		20-1950-AC

Crash Data Summary Table


Warren Avenue at Market Street, Brockton, MA

2017-2021

Crash Diagram	Crash Date	Crash Day	Time of Day	Manner of Collision	Light Condition	Weather Condition	Road Surface	Driver Contributing Code	Ages		Ages	
Ref #	m/d/y			Туре	Туре	Туре	Туре	Туре	D1	D2	D3	
65	2/20/21	Saturday	3:01 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	37	26		21-252-AC
66	3/13/21	Saturday	3:14 PM	Angle	Daylight	Cloudy	Dry	No Improper Driving	27	24		21-343-AC
67	3/29/21	Monday	2:12 PM	Angle	Daylight	Clear	Dry	Failed to yield right of way	44	20		21-448-AC
68	4/19/21	Monday	9:13 AM	Angle	Daylight	Clear	Dry	Failed to yield right of way	75	21		21-588-AC
69	4/26/21	Monday	5:20 AM	Angle	Unknown	Clear	Dry	Unknown	49	34		21-638-AC
70	5/22/21	Saturday	4:40 PM	Angle	Daylight	Clear	Dry	No Improper Driving	25	28		21-801-AC
71	6/5/21	Saturday	6:21 PM	Angle	Daylight	Clear	Dry	Unknown	59	21		21-894-AC
72	6/9/21	Wednesday	11:52 AM	Angle	Daylight	Clear	Dry	Other improper action	57	57		21-917-AC
73	6/14/21	Monday	7:18 PM	Angle	Dusk	Rain	Wet	Failed to yield right of way	66	38		21-966-AC
74	6/15/21	Tuesday	2:12 PM	Angle	Daylight	Cloudy	Dry	Failed to yield right of way	21	24		21-971-AC
75	7/3/21	Saturday	6:15 PM	Angle	Daylight	Rain	Wet	Failed to yield right of way	52	28		21-1096-AC
76	7/30/21	Friday	3:09 PM	Sideswipe, same direction	Daylight	Clear	Dry	Failed to yield right of way	60	27		21-1275-AC
77	8/11/21	Wednesday	1:14 PM	Sideswipe, opposite direction	Daylight	Cloudy	Dry	Unknown	73	27		21-1381-AC
78	9/3/21	Friday	6:25 PM	Single Vehicle Crash	Daylight	Clear	Dry	Unknown	51	34		21-1556-AC
79	9/17/21	Friday	7:12 AM	Angle	Daylight	Clear	Dry	Failed to yield right of way	33	20		21-1652-AC
80	12/2/21	Thursday	6:42 PM	Angle	Dark - lighted roadway	Clear	Wet	No Improper Driving	18	21		21-2198-AC

*Courtesy Crash - A term used to describe a crash that occurs subsequent to a non-involved mainline driver who gives the right of way, contrary to the rules of the road, to another driver.


Crash Data Summary Tables and Charts




Warren Avenue at Market Street, Brockton, MA

Crash Data Summary Tables and Charts

Warren Avenue at Market Street, Brockton, MA





Appendix D. Additional Information

Appendix E. Road Safety Audit References

Road Safety Audit References

- *FHWA Office of Safety Proven Safety Countermeasures,* U.S. Department of Transportation, Federal Highway Administration <u>https://safety.fhwa.dot.gov/provencountermeasures/</u>.
- *Road Safety Audits, A Synthesis of Highway Practice.* NCHRP Synthesis 336. Transportation Research Board, National Cooperative Highway Research Program, 2004.
- *Road Safety Audits*. U.S. Department of Transportation, Federal Highway Administration, <u>https://safety.fhwa.dot.gov/rsa/</u>
- *FHWA Road Safety Audit Guidelines*. U.S. Department of Transportation, Federal Highway Administration, 2006.

Road Safety Audit, 2nd edition. Austroads, 2000.

Road Safety Audits. ITE Technical Council Committee 4S-7. Institute of Transportation Engineers, February 1995.